

VEHICLE INSPECTION REPORT

WS19AAV

Fiat Ducato 35 2.3 II MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 06/08/2019

Year 2019

Mileage 130,126 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZFA25000002L47430

Body Style Panel Van MWB

MOT Due 15/06/2027

CAP Clean £4,000.00

CAP Average £3,450.00

CAP Below £2,700.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, TOW BAR, DEADLOCKS, RACKING IN REAR

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Wing nsf
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Dented
Over 30mm

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



9: Qtr Panel osr
Dented
Over 30mm

10: Door Pad osf
Soiled
Heavy



11: Carpets Front
Holed
Over 3mm

12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			