

VEHICLE INSPECTION REPORT

SL23GLK

Ford Transit 310 2.0 EcoBlue 130ps Trend

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/05/2023

Year 2023

Mileage 51,948 Miles Not Warranted

Fuel Type Diesel

Colour GREY

VIN WF0EXXTTREP63797

Body Style Panel Van LWB

Keys 2

MOT Due 29/05/2026

CAP Clean £14,600.00

CAP Average £13,800.00

CAP Below £12,150.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

AD- BLUE

Tyres

NSF

NSR

OSF



OSR



Spare

Features


- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Qtr Panel or
Dented
Over 30mm



3: Sill os
Dented
Over 30mm



4: Tailgate
Dented
With Paint Damage



5: Door nsr
Dented
Over 30mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK